ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone

YELAHANKA

Ward No.

3

Ward Name

Atturu

Street ID

W0384, W0705, W0380, W0374, W0366, W0370, W0699, W

Street Name

Own Use Rd, NA, 9th Crs Lakshmi Sagar Lyt, 1st Main Rd, S Krishnappa Lyt

Significant Landmark

Attur layout 6th 7th 8th and 9th main road

Segment No.

3/C-W0384/S110241

Total Length (m)

1028.20

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	447.54	77.567717	13.102087	77.567492	13.098048	M0008	W0336
2	430.70	77.568055	13.098111	77.568296	13.101996	M0008	W0336
3	149.96	77.568645	13.098174	77.568726	13.099527	M0008	W0380

Work Details

History of Road / Lane / Circles

Name of the Work

Asphalting to Roads and Improvements to Drain in Attur layout 6th 7th 8th and 9th main road in ward no 03 Yelahanka Satellite Town Sub division Yelaha

Sanctioned Estimated Amount (Rs.)

7500000

Sanctioned Year

2017

Year

2017 - 2018

Type of Work

Asphalting

Other Work Type

Tender

Not a Tender

Work Details

Asphalting to Roads and Improvements to Drain in Attur layout 6th 7th 8th and 9th main road in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code

003-17-000011

Work Order No.

BBMP/EE (YNK.D) /WO/143/2017 -18

Work Order Date

31/03/2017

Period of Extention

90 DAYS

Defect Liability Period From

30/04/2017

Defect Liability Period To

29/04/2018

Multiple road involved with the same Job No/ Work Code #

Yes

Contractor Details

Name of Contractor

KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

0.00

9449863065 E-Mail ID

Field Inspection Details

Number of Trees

6

Any Other Information

Name

CHANDRAKANTH

Date of Inspection

24/05/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0384, W0705, W0380, W0374,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/05/2017	23/06/2017	COMPLETED
SE	VASU K M	24/05/2017	23/06/2017	COMPLETED
EE	VASU K M	24/05/2017	23/06/2017	COMPLETED
AEE	ASHOK	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alturu **Street ID:** W0384, W0705, W0380,